



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION 5

230 SOUTH DEARBORN ST.

CHICAGO, ILLINOIS 60604

REPLY TO THE ATTENTION OF:

5HR-11-SSI

Katherine Davidson
~~Mark Beset~~, Supervisor
Federal Sites Coordination Unit
Office of Corrective Actions
Ohio Environmental Protection Agency
1800 WaterMark Drive
Columbus, Ohio 43266-0149

Site Name: South Dayton Dump

Location: Moraine, Ohio

U.S. EPA ID#: OH0900611383

Date: 7/26/91

Dear Mrs. Davidson:

Attached is a copy of the screening site inspection report (SSIR) which has been prepared for the site listed above. This document is considered to be draft and subject to changes and modifications based on comments made by your agency and the U.S. Environmental Protection Agency (U.S. EPA).

Because this is considered to be a draft document, it should be for official use only and should not be distributed outside of your agency without prior notification and approval of the U.S. EPA.

Enclosed with this document is a revised estimate of the Hazard Ranking System (HRS) score for the site based on additional information gathered during the SSI and the preparation of the SSIR. This information is considered pre-decisional. Therefore, it should not be released. Your field and district staff especially should be made aware of the predecisional nature of this score and the legal implications of releasing it relative to the National Priorities List (NPL) candidacy process. If you have any questions concerning release of this information, please contact Ms. Jeanne Griffin, of my staff, at (312) 886-3007.

If you have any comments concerning the SSIR, please contact Mr. Bill Messenger, of my staff, at (312) 353-1057, within 30 calendar days. Please contact Bill as early in the 30-day period as possible to ensure that your comments can be evaluated and modifications made. If we do not receive any comments, written or verbal, from you, we will assume that the SSIR is acceptable and should be finalized. U.S. EPA will then release a final SSI report.

Sincerely yours,

Thomas F. Geishecker

Thomas F. Geishecker
Technical Support Section
Enclosure

cc: Bill Messenger
Ohio-EPA District Office
1187:4

EPA Region 5 Records Ctr.



255580